

STRAIGHT LINE (standard)



SLIGHT CURVE (Might be feasible using straight glass panels)




SHARP CURVE (or spiral) (Not suited for glass railings using straight glass panels)



STRAIGHT LINE (standard)



SLIGHT CURVE (Might be feasible using straight glass panels)






SHARP CURVE (or spiral)
(Not suited for glass railings using straight glass panels)

Too much waste of space Not pleasant/professionally looking Excessive cutting



Hardware (of any kind) won't be installed flat on the curved fascia.



There's no alignment between hardware in order to install the glass.

